


DICOM Correction Proposal

STATUS	Assigned
Date of Last Update	2024/11/02
Person Assigned	Clunie
Submitter Name	Jeroen Medema, jeroen.medema@philips.com
Submission Date	2024/06/28


Correction Number	CP-2441
Log Summary:	remove the word 'codes' from diagrams
Name of Standard	PS3.18
Rationale for Correction:	The sequence diagrams of the proxy examples in PS3.18, B.30 use the phrase 'result codes' colloquially while this would be better phrased 'result' as not always codes are contained in what is yielded. This requires an update of these diagrams.
Correction Wording:	See below. Note that the changes are shown in a descriptive and graphical way, not using the standard convention of new text and deleted text .

Changes in diagram B.30-1


Change



by doing




to




Changes in diagram B.30-2

Change



by doing



to

